

Installing the Scanner

To install the L-Tron scanner on your Toughbook, you will first need to install the drivers and then configure the scanner. Follow these steps:

1. Plug in the scanner into a USB port on the Toughbook.
2. Windows will try to location a driver for download. **Cancel this as the driver is not needed.**
3. Each scanner comes with a booklet containing several barcodes. The two you will need are located in the upper right hand corner.
4. First scan the barcode that says, “Reset to Defaults”.



Reset to Defaults

5. The scanner will restart. Once it comes back online, scan the second barcode labeled, “USB HID Interface”.



USB HID Interface